




# Datum Tags

How to attach a Datum Tag to a dimension for a center plane callout. From within the drawing.








But you have to start from the part.






## PART

1. Check the Layer Tree, that the 1\_DTM\_PLANE is **not hidden**.
2. Unhide the layer and **Display the Planes**.
3. Select the **Annotate Tab**.
4. Select the **FRONT** Annotation Plane. The orientation of the datum tag.
5. Select **Active Annotation Plane**.
6. Select **Annotation Feature**.
7. Select **Set Datum Tag**.




8. Enter the Datum Tag letter **C**.
9. Toggle on Reference **Datum**.
10. Toggle on Placement **On Datum**.
11. Select the **Datum Plane** on the part, or from the **Detail Tree**.
12. OK
13. OK
14. Save frequently and often.





**Note:** In this example the datum tag goes on the datum plane, to indicate the center datum plane. All other datum tags must be on the part surface.

## DRAWING

1. Go to the Drawing.
2. Select the **Annotate tab**.
3. Erase the Datum tag in the views you do not want it displayed.




4. Select the **Datum tag** from the displayed datum plane, Right Mouse Button select **Properties**.
5. Select **In Dim => Pick Dim**
6. Pick the **dimension** for the Center Plane.
7. Flip Witness Line if necessary.




8. The Datum Tag triangle base lines up with the dimension arrow head.
9. This means the datum plane C is at the mid-plane of the dimension.
10. This is called Datum Plane C.
11. A Datum Tag is **NEVER** place on a center line. Even though CREO allows this behavior to occur.




### Add tolerance.

1. Add Plus .002 and Minus 0 tolerance.




### Add GD&T Position Feature Control Frame.

1. Select the **Annotate** tab.
2. Select the **Geometric Tolerance**.
3. Select **Position** .
4. Select the **Datum C** from the Model Tree.



# Datum Tags move

1. After the GD&T Position is applied the Datum Tag moves to the Feature Control Frame.



## To many decimal places.

Select the dimension => RMB => properties.

Check Rounded Dimension Value to get metric dims to two decimal places.

The image shows a CAD software interface with a dimension line and its properties. The dimension line is labeled 'A' and has a value of .781 and a tolerance of [0.05]. A red arrow labeled 'B4' points to the dimension value. The bottom part shows the same dimension line with a value of .781 and a tolerance of [0.05]. A red arrow points to the dimension value. The right part shows the 'Dimension Properties' dialog box with the 'Rounded Dimension Value' checkbox checked and the 'Decimal Places' field set to 2.

**Dimension Properties**

Properties | Display | Text Style

Name: d12

**Value and Display**

- Nominal Value: 0.781
- Override Value
- Tolerance Value Only
- Rounded Dimension Value

Decimal Places: 3

**Format**

- Decimal  Fractional
- Angular dimension units: (As Is)

**Tolerance**

Tolerance mode: Nominal

Upper tolerance: +0.010

Lower tolerance: -0.010

Decimal Places:  Default 3

**Dual dimension**

Position:  Below  To right

Decimal Places: 2




Tolerance Decimal Places:  Default

Buttons: Move..., Move Text..., Edit Attach..., Orient..., Text Symbol..., Restore Values, OK, Cancel




**AFTER**

## To change the orientation of the annotation.

From the **PART**



1. Right click on the dimension leader line.
2. Select Pick From List.
3. Select OK.
4. Right click on the dimension leader line.
5. Select Current Orientation.



Things PTC never tell you, or I cannot find them.

1. Cross sections can NOT be used to place datum tags. Select a feature view to place the GTOL or datum tag then RMB to get the menu Move item to view.
2. Check this setting in File => Prepare => Drawing Properties => asme\_dtm\_on\_dia\_dim\_gtol = on gtol or on dim.
3. Do not add a datum tag to the primary datums. Create a new datum for the datum tags by selecting a surface or axis and let that datum do that and only that. Their behavior for showing and not showing is a bit more predictable. I have found the paradox with always shown datums w/ tags in the model will flip when you show that datum in a drawing.
4. If the model datums are hidden, any associated geotol will not show in the drawing, period.
5. From what I've experienced, it may be best to create the geotols in the drawing once the datum tags are established in the model.
6. The take-away was that applying datum tags to primary datum planes makes them difficult to hide. However, if you create datum tags on Geometry, Creo creates datum planes for that purpose behind the scenes and therefore, they can be hidden more easily. So create datum surfaces to make the tags more controllable.
7. In the model. Add the datum axis tag to a separate layer.  
Then in the drawing.  
Right-click & select properties -> Drawing Options  
set the option **drawing\_layer\_overrides\_model** to yes  
get the name of the view (e.g. TOP)  
View the layers in the model tree area  
In the drop-down box, select the view  
Select the layer with the datum axis & hide. Save layer status. Save drawing.



8. Using standard iso/ansi settings, the datum flag will be placed on the diameter, and standard asme settings the flag will be placed on the shoulder of the leader line facing up, or on the diameter, and if you have a control frame attached to the dimension in asme settings it will point downward off the center of control frame with a plunger, and if you use standard ansi settings there is no plunger extending from the control frame.
  
9. After filing a tech support case I found that PTC actually intends is that the ANSI Y14.5M-1982 datum style button is used for 2D drawing annotations and the ASME Y14.5M-1994 style button is used for 3D datum annotations. The layer issue with the ASME Y14.5M-1994 style selection (3D annotations) is in debate whether it will be fixed in Creo 4.
  
10. PTC please change the confusing symbology in the datum properties dialog box so that it differentiates between 2D and 3D annotations without confusing users with ANSI and ASME standards.

11. Currently, the datum properties dialog box shows 3 buttons: a regular datum, an ANSI Y14.5M-1982 datum and an ASME Y14.5M-1994 datum. Users frequently mistake these symbols to mean that if you select one of these buttons, the datum will conform to that standard. Unfortunately, the ASME Y14.5M-1994 style button creates an annotation that cannot be hidden on a layer and frequently does not show up correctly in drawings.

The diagram shows the 'Datum' dialog box with three callout boxes: 'ANSI 1982 Datum' pointing to the '-A-' symbol, 'Unset Datum' pointing to the 'A' symbol, and 'ASME 1994 Datum' pointing to the 'A' symbol with a left-pointing arrow.

**-A-**

- Does not change datum style.
- Shows up in drawings correctly.

**A** ←

- Does not change datum style.
- Does not show up in drawings correctly.
- Always visible in models despite layer settings.

Used before 1994, ANSI

## Datum Tags in the drawing

1. Datum Tags do not always highlight when hovering over them with the cursor. Select the annotate tab, go ahead and Left Mouse Button, LMB, on the datum letter to select it. A small white square will appear, then hover the cursor over it and the datum tag will now highlight.
2. Datum tags will NOT display on another sheet of multi sheet drawings if the datum tag is attached to a dimension or the feature control frame, FCF, of a geometric tolerance.